



STATE OF NEW YORK  
DEPARTMENT OF TRANSPORTATION  
ALBANY, N.Y. 12232

WWW.DOT.NY.GOV

JOAN McDONALD  
COMMISSIONER

ANDREW M. CUOMO  
GOVERNOR

May 16, 2013

OPERATOR ID 02138

SOUTHERN TIER MEDI-VAN  
PO BOX 978  
VESTAL, NY 13850-0978

Dear Motor Carrier:

Enclosed is the annual New York State Department of Transportation Bus Inspection System Operator Profile that summarizes the results of vehicle inspections performed on your fleet by the Department during the last State Fiscal Year (April 1, 2012 to March 31, 2013). For regularly scheduled inspections, the profile identifies the number and percentage of vehicles that passed or were placed Out-of-Service (OOS) due to one or more OOS defects. It is the Department's continued goal to have all operators pass at least 90% of their scheduled safety inspections. The statewide average OOS rate is 5.8%.

For those operators with at least ten or more regular inspections, and whose OOS rate is 25% or greater you are now put on notice that you fall under the Department's enforcement program. If you have not been notified already, you will be contacted to address your unacceptable performance. Actions may include civil penalties, unannounced vehicle inspections, denial of B & C privileges, compliance reviews or other corrective actions.

Operators that have a passing rate of less than 90%, it is requested that your organization examine the enclosed profile inspection data and immediately update your maintenance program to reduce your OOS Rate to meet our goals. Your Regional Bus Inspection Program Supervisor is available to review the actions being taken and provide assistance if necessary.

We congratulate those operators who have achieved the goal of a 90% or greater pass rate. Your commendable performance indicates a strong dedication to safety and a commitment to sound maintenance standards and practices.

97.9

For additional program information please visit: <https://www.dot.ny.gov/divisions/operating/osss/bus>

Sincerely,

Lawrence Scotto, Acting Director  
Passenger Carrier Safety Bureau

Enclosures

cc: Regional Bus Program Supervisor